

Technical Brief

No. 040216

X-Tension 350 Yellow Nose Affixment

Overview:

In adverse weather conditions the X-Tension 350 yellow nose piece can become loosened and sometimes detached from its mounted position.

To overcome the risk noted in regions which experience adverse weather, installers may fix self-tapping Tek screws to the nose piece to secure it the X-Tension 350 head.

Rectification:

Using a drill driver, fix no more than two self-tapping Tek screws on each side of the X-Tension 350 on the edges where the nose piece covers the X-Tension 350 head piece as shown below.

